

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00966
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico for Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88249		7. Lease Name or Unit Agreement Name Artesia Metex Unit 51
4. Well Location Unit Letter <u>P</u> : <u>330</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>26</u> Township <u>18S</u> Range <u>27E</u> NMPM Eddy County		8. Well Number
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864
		10. Pool name or Wildcat Artesia QU-GB-SA

HOBBS OCD
JUN 10 2019
RECEIVED

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX
CASING/CEMENT JOB ☐

PRR

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Kerry Forth TITLE Compliance Officer A DATE 6-14-19
Conditions of Approval (if any): _____

Plugging Report
Artesia Metex Unit
API 30-015-00966

5/27/2019 Cleared location with backhoe and tested anchors. Moved in rig and rigged up. Repaired casing stub by welding old wellhead from the #46 on it. Installed BOP. Moved in workstring and remaining equipment. RIH with workstring to 1365' and SION.

5/28/2019 Moved in remaining equipment. Spot 50 sx cement with CaCl at 1365'. WOC and tagged cement at 1239'. Pumped MLF. No fluid to surface. POOH with tubing and remove BOP. Dumped 3 yards gravel. Tagged with tubing at 992'. Dumped 2.7 yards gravel. Tagged at 774'. Dumped 2.7 yards gravel. Tagged at 564'. Installed BOP and caught circulation with 5 bbls. Lost circulation after 2 more bbls. Spot 25 sx cement with CaCl at 564'. POOH and SION.

5/29/2019 Tagged cement at 512'. Well would not circulate. Spot 25 sx cement with CaCl at 512'. WOC and tagged cement at 425'. Pumped 30 bbls to get circulation. Last 5 bbls had a trickle to the pit. Spot 50 sx cement with CaCl. Laid down remaining pipe and rigged down. SION

5/30/2019 Filled up 8 5/8" casing from the top with 65 sx cement. Cut off wellhead and installed marker. Cut off anchors and cleared the location.