Submit 1 Copy To Appropriate District Office	Stat	e of New Me	xico	<b>`</b> D	Form C-103
District I - (575) 393-6161	Energy, Min	erals and Nat		WELLABING	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283				WELL API NO.	-025-46347
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178		SERVATION South St. Fran	DOVERS 2050 2019	5. Indicate Type of I	Lease
1000 Rio Brazos Rd., Aztec, NM 87410				STATE X	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	San	ila re, ivivi o	RECEIVE	State Oil & Gas L	ease No.
87505					
SUNDRY NOT (DO NOT USE THIS FORM FOR PROP	FICES AND REPOR			7. Lease Name or Ur	it Agreement Name
DIFFERENT RESERVOIR. USE "APPL				Duck Hunt 1 S	tate Com
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other				8. Well Number	602H
2. Name of Operator				9. OGRID Number	00211
Centennial Resource Production, LLC					72165
3. Address of Operator				10. Pool name or Wi	
TOUT 17th Street, suite 1800, Denver, CO 80202				Antelope Ridge, Bone Sp	nng, North
4. Well Location  Unit Letter J : 2339 feet from the S line and 1985 feet from the E line					
Unit Letter J Section 1	1001 II 01.				
Section			nge 34E		ounty
11. Elevation (Show whether DR, RKB, RT, GR, etc.)  3366 GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK		IDON 🗆	REMEDIAL WORK		TERING CASING
TEMPORARILY ABANDON		=	COMMENCE DRIL	_	AND A
PULL OR ALTER CASING	MULTIPLE COMF		CASING/CEMENT	JOB 🗀	_
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM Si	] detrack	(3)	OTHER:		-
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
H&P 650 drilled the 8-1/2" lateral to a depth of 15825'MD. Proposed Total Depth for the well is 19439'MD. After encountering slow ROP, the BHA was tripped					
to surface and discovered that several components of the Rotary Steerable Tool had separated from the tool and were left downhole. These items are non-mag in nature and cannot be fished by magnets. Furthermore, due to the size and shape of the debris, additional fishing operations were deemed					
high risk. Sidetrack operations are planned at a depth of 13763'MD and will place the sidetrack hole not more than 50' away from the original hole with in-					
tended BHL as permitted previously. After the lateral is drilled to Total Depth, 5-1/2" Production casing will be run and cemented to surface, effectively isolating the abandon portion of the lateral.					
Sand Date		D's Dalassa Da			
Spud Date:		Rig Release Da	ite:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
1. 03					
SIGNATURE K. L.		m:m:			
SIGNATURE		HILE Sr. R	egulatory Analy	<u>rst</u> DATE	10/25/18
Type or print name Kanicia	Schlichting	E-mail address	: kanicia.schlichting	@cdevinc.com PHON	IE: <u>720-499-1537</u>
For State Use Only				<u></u>	
APPROVED BY:	tonthe.	TITLE C. O	A	<b>-</b>	10-25-19
APPROVED BY: Conditions of Approval (if any):	, , , , , , , , , , , , , , , , , , , ,	111LE <u>C, V</u>	<u>, , , , , , , , , , , , , , , , , , , </u>	DATE	10 /