Form 3160-5 (June 2015)

_Approved By_JQNATHON SHEPARD

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

Datc 07/22/2020

BUREAU OF LAND MANAGEMENT						nuary 31, 2016
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals BBS OC					5. Lease Serial No. NMLC029409A	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2 JUL 3 0 20					7. If Unit or CA/Agree	ment, Name and/or No.
1. Type of Well Gas Well Other RECEI					8. Well Name and No. PEARSALL AX 08	
2. Name of Operator	MELANIE REY	ES PREC		9. API Well No.		
LEGACY RESERVES OPERA	.com 30-025-36364-00-S1					
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-221-6358			10. Field and Pool or Exploratory Area MALJAMAR		
4. Location of Well (Footage, Sec., T.)		•	11. County or Parish, State		
Sec 33 T17S R32E NWSW 23				LEA COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE	NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
☑ Notice of Intent	☐ Acidize	☐ Deeper	1	☐ Product	tion (Start/Resume)	☐ Water Shut-Off
	Alter Casing	☐ Hydrai	lic Fracturing	Reclamation		☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New C	onstruction	Recomplete		Other
☐ Final Abandonment Notice	☐ Change Plans	— ☐ Plug a	☐ Plug and Abandon ☐ Temporarily Abandon		rarily Abandon	
	Convert to Injection	☐ Plug Back ☐ Water		☐ Water I	Disposal	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to decepen directionally or recomplete horizontally, give substract locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandomment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. We are requesting the subject well be placed in TA status for four years due to the current situation the oil industry is in. POH with production equipment. RIH with CIBP. Set CIBP at 4,026' and cap with 35' of cement. Tag cement top. Circulate well and load casing with inert fluid. Notify BLM for MIT and perform MIT on well. Wellbore diagram attached.						
14. I hereby certify that the foregoing is	true and correct.	E24227	w the DI M Mr.	l Informati-	- Swatam	
Electronic Submission #521237 verified by the BLM Well Information System For LEGACY RESERVES OPERATING LP, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 07/08/2020 (20PP2973SE)						
Name (Printed/Typed) STEPHEN	•			n 07/08/2020 SINEERING	,	
Tanon Types OTEPHEN	TOTALIA		JN EN	JINEERIING	ADTIOON	
Signature (Electronic S	Submission)		ate 07/07/2	020		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) *** BLM REVISED ** BLM REV

TitlePETROELUM ENGINEER

Office Hobbs

Revisions to Operator-Submitted EC Data for Sundry Notice #521237

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

TA NOI

Lease:

NMLC029409A

TA NOI

NMLC029409A

Agreement:

Operator.

LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701 Ph: 432-689-5200

Admin Contact:

MELANIE REYES COMPLIANCE COORDINATOR

E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Tech Contact:

STEPHEN OWEN SR ENGINEERING ADVISOR

E-Mail: sowen@legacyreserves.com

Ph: 432-689-5200

Ph: 432-221-6358

STEPHEN OWEN SR ENGINEERING ADVISOR

E-Mail: sowen@legacyreserves.com

LEGACY RESERVES OPERATING LP 303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686.8318

MELANIE REYES
COMPLIANCE COORDINATOR
E-Mail: mreyes@legacyreserves.com

Ph: 432-689-5200

Location:

State: County:

NM LEA COUNTY

Field/Pool:

MALJAMAR; GRAYBURG-SA

NM LEA

MALJAMAR

Well/Facility:

PEARSALL AX 8 Sec 33 T17S R32E NWSW 2310FSL 990FWL

PEARSALL AX 08

Sec 33 T17S R32E NWSW 2310FSL 990FWL

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.

Lease & Well # Pearsall AX #8

SPUD- 10/9/03

KB-Elevation - 3904' G 13 3/8" H-40 48# ST&C @ 323", 350 sx C, circ 38 sx. 8 5/8" 32# 8rd J-55 STC @ 2214, 850 sx 35/65/6, 200 C, circ 92 sx.

DV Tool - 3904'

GB/SA

4075.5- 4343.5 22 holes Acidized w/2500 gal 15% NEFE Fraced w/106,000 gal lg, 127,080 # sd

Marker jt - 4485'

4465-4486 7 holes

Cmt retainer-4640®

San Andres

Acidized w/700 gal 15% NEFE, squeezed off w/100 sx.

4677.5-4728.5 22 holes

Acidized w/2500 gal 15% NEFE, frac w/17,304 gal Ig,a 20,846 # sd

Squeezed off w/120 sx

PBTD - 5070'

1st stage: 260 sx 50/50/2, circ 64 sx.

2nd stage: 450 sx 35/65/6, 250 sx 50/50/2, circ 84 sx

5 1/2" 17# J-55 ST&C csg @ 5083'.