

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-041-10016

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

LC-060978

7. Lease Name or Unit Agreement Name:

Milnesand Sand Andres Unit8. Well No. **126**

9. OGRID Number

10. Pool name or Wildcat

Milnesand (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Thompson, J. Cleo

3. Address of Operator

P. O. Box 12577, Odessa, TX 79768-2577

4. Well Location

Unit Letter **D** : **660** feet from the **North** line and **660** feet from the **West** line
Section **7** Township **8S** Range **35E** NMPM County **Roosevelt**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☒
 CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/5/06 WIH w/ 3/8 work string o 4592. No tag.

10/6/06 Circ. hole w/ mud laden fluid. Spot 40 sx cmt @4592. WOC 4 hrs. Tag plg @ 3952.

10/9/06 Perf. 4 1/2 csg. @ 2350. Set AD 1 packer @ 2061. Establish rae of 3 bbls/min. Sqz 8 sx cmt. displace to 2250 w/ 600 psi. WOC 3 hrs. SDFN.

10/10/06 Tagged plug @ 2252. Per. csg. @ 1850. Set packer @ 1523. Sqz. 80 sx cmt. WOC hrs. Tag plg @ 1738. Lost packer in hole. Perf. csg. @ 420'. Circulated 140 sxcm. down 4 1/2 annulus and up 8 5/8 csg. WOC.

10/11/06 Cement @ surface. Cut off wellhead. Install Dry Hole Marker. clean loc Rig down.

Approved as to plugging of the Well Bore.
 Liability under bond is retained until
 surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

John P. Hughes

TITLE

Foreman

DATE

10-24-06

Type or print name

E-mail address:

Telephone No.

For State Use Only

APPROVED BY

Larry W. Wink

FILE

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

NOV 02 2006

Conditions of Approval (if any):