

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-00408
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8233
7. Lease Name or Unit Agreement Name: TIPTON UNIT
8. Well Number 15
9. OGRID Number 013837
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 MACK ENERGY

3. Address of Operator
 P.O. BOX 960, ARTESIA, NM 88211-0960

4. Well Location
 Unit Letter O : 330 feet from the SOUTH line and 2310 feet from the EAST line
 Section 30 Township 16S Range 32E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application or Closure

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
Approved as to plugging of the Well Bore. Liability under bond is retained until COMPLETION	OTHER: <input type="checkbox"/>
OTHER: surface restoration is completed. <input type="checkbox"/>	OTHER: surface rest. <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 10-27-06 Set pkr. @1,512'. Sqz. 150sx cmt.
- 10-30-06 Tag plug @1,720'. Perf. 4 holes @1,080'. Set pkr. @700'. Sqz. 100 sx. cmt. Tag plug @ 933'. Perf. 4 holes @378'. Set pkr. @60'. Sqz. 100 sx. cmt.
- 10-31-06 Tag plug @150'. Spot 10 sx. cmt. from 60' to surface.
- 11-1-06 Install Dryhole Marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan

SIGNATURE Randall Minear TITLE P & A Supv. DATE 11-3-06
 E-mail address: _____ Telephone No. 432-530-0709

For State Use Only
 APPROVED BY Gayle W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE DEC 12 2006
 Conditions of Approval, if any: _____