Office Submit 3 Copies To Appropriate District	State of Ne			Form C-103		
District J	Energy, Minerals and Natural Resources			Revised May 08, 2003		
1625 N. French Dr., Hobbs, NM 88240	0			WELL API NO. 30-025-22490		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION					
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE X FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505				STATE X FEE 6. State Oil & Gas Lease No.		
District IV 1220 S. St. Francis, Santa Fe, NM						
87505				B-4118		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name Lea		
PROPOSALS.) 1. Type of Well:				8. Well Number		
Oil Well X Gas Well Other				23		
2. Name of Operator				9. OGRID Number		
ConocoPhillips Company				217817		
3. Address of Operator 4001 Penbrook Street Odessa TX 79762				10. Pool name or Wildcat		
3. Hadress of operator foot I shorook shoot substantial for				Vacuum; Grayburg-San Andres		
4. Well Location						
Unit Letter P 510	feet from the So	outh	line and 810	feet fi	rom the East	line
C (' 20 T L' 17 C P 24 F					0	
Section 30	Township 17-S		nge 34-E	NMPM	County Lea	T. SEC. BLICK
**************************************	l. Elevation (Show wheth 4083'GR,4103'KB	er DK, K	KB, RT, GR, etc.)			
		anto M	ature of Notice I	Panart or Otha	r Doto	
12. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO:						-72
			SEQUENT R	ALTERING C		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				`	ARMERING	Moing of
TEMPORARILY ABANDON				LLING OPNS.	PLUG AND CABANDQNM	,,
PULL OR ALTER CASING MULTIPLE CASING TEST A			ND 🗆	To the state of th		
C	OMPLETION		CEMENT JOBS		Cos.	
OTHER:	[OTHER: Re-Comp	olete and Test Mo	Knight	[3]
13. Describe proposed or completed	d operations. (Clearly st	ate all p	<u>-</u>			stimated date
of starting and proposed work).						
or recompletion.						
7/18/03 Pull rods & tubing						
7/21/03 Removed WellHead and installed BOP - Rigged up Scan-A-Log - POOH Inspecting Tubing - (80 jts. Yellow Band - 7 jts.						
Blue Band - 15 jts Green Band - 10 jts. Red Band) - Rigged down Scan-A-Log 7/22/03 RIH w/Scraper						
7/23/03 Cont. RIH w/Scraper to top of cement @ 5,221' - Broke circualtion w/32 bbls. of water - POOH and laid down Scraper -						
Picked up and RIH w/8 5/8" Packler and set @ 4,993' - Tested Cement Plug to 500# for 30 mins (Held) - Released Packer and						
pulled up hole and set Packer @ 4,334' - Load backside and tested Casing to 500# for 30 mins (Held) - Released Packer and POOH.						
7/24/03 Picked up Bit, and Drill collars and RIH on 2 7/8" Workstring and tagged Cement Plug @ 5,221' - Rigged up Reverse Unit						
and Power Swivel - Broke Circulatio	n and started drilling on	plug - l	Drilled out to 5,322'	- (Got back both	n hard and soft ce	ement in
returns) - Circulated Well Clean. 7/25/03 Dropped down and tagged co	ement @ 5 321' - Broke	circulat	ion and started drill	ing on coment I	Fall out of camer	st @ 5 547!
Cont. RIH to 5,890' - (Well kicked) -		Circulat	ion and started drin	ing on cement - i	ren out of cemer	II (<i>a</i>) 3,347 -
7/28/03 Dropped down and Tagged of		- Cont. 1	Drilling on cement -	Drilled out to 5.	986' - Circulated	l Well clean -
Laid down Power Swivel - POOH as	nd laid down Drill Colla	rs and E				
Workstring - Set Packer @ 5,343' - (1	Bottom of Tail Pipe @ 5	,850')		-		
	***************************************		nued on the backof			
I hereby certify that the information above	ve is true and complete t	to the be	est of my knowledge	e and belief.		
SIGNATURE DIME	_ TI	rr Ad	lmin Assistant		D. A TIP. 10/0	12/2002
SIGNATURE LAUGE STA	nesII	ILE AC	IIIII Assistant		DATE_ 10/0	
Type or print name Alva Franco				Tele	phone No. (432)368-1665
(This space for State use)					OCT A	
APPROVED BY LOW IN WIND OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE OF 2003						
Conditions of approval, if any:						
Conditions of approval, in this.						

Lea #23 Continued from item #13

7/29/03 Rigged up Swab - RIH and Tagged fluid @ 300' - Made 30 runs and recovered a total of 220 bbls. of Water - Ending Fluid Level @ 2,600' from surface 7/30/03 RIH w/Swab and tagged fluid @1,600' from surface - Made 26 Runs and recovered 176 bbls. total of Dirty Water - Ending FL @ 3,600' from Surface 8/01/03 RIH w/ Swab - Tagged fluid @ 2,600 ft from surface - Made 25 runs recovered 169 bbls all water - Ending fluid level @ 3,600 ft from surface 8/04/03 COOH W/ packer laying down work string 8/05/03RIH W/ rods - COOH laying rods down - ND BOP - NU wellhead - RD DDU - Clean location. Left well shut-in, notice of intend to plug and abandonment filed w/NMOCD pending approval.