Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised June 10, 2003 WELL API NO.
District II	OIL CONCEDIVATION DIVISION		30-025-26854
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Brazos Rd., Aztec, NM 87410 Santa Fa NM 87505		STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		o. State Oil & Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			, and the second
PROPOSALS.)			Leavelle 8. Well Number
1. Type of Well: Oil Well X Gas Well Other Approved as to plugging of the Well Bore.			8. Wen Number
Tillia 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1	
2. Name of Operator		9. OGRID Number	
Gandy Corporation surface restoration is completed. 3. Address of Operator			10. Pool name or Wildcat
P.O. Box 827 Tatum NM 88267		N. Shoe bar Wolfcamp	
4. Well Location			
Unit LetterB:660_ feet from theN line and1980 feet from the			
E line			
Section 23	Township 16S	Range 35E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3984.5 RKB			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	C ALTERIÑŒ, CASING □
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII	
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	ID TO ABADDONMENT
_	COMPLETION CEMENT JOB		\& _ \\ \& \\ \& \\ \& \\ \& \\ \\ \& \\ \\
OTHER:		OTHER:	
	eted operations. (Clearly state all	pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. Move in equipment and run tubing in hole open ended. Tag up at 4898'. Hook up reverse unit and power swivel.			
Establish Circulation with 30 bbls of fresh water. Tubing would plug up when weight was applied. Pulled tubing find that			
joint was turning on something metal. GIH with 4 1/4" impression block. Passed beside object in hole. COOH with			
Impression Block. Could see scrapes on sides of IB. GIH with 6 1/2" IB and tag up. COOH with IB and Find that			
something like casing or pipe laying over on side of hole. Talk to Billy Prichard with Hobbs OCD and ask to go ahead and set cement plugs. Got Verbal OK. GIH with tubing open ended @ 4850'. Circulate hole with mud. Mix up 50 sxs of cement			
and pump. Follow by 28 bbls flush to put on spot. COOH with tubing. Wait 24 hrs. GIH with tubing and tag @ 4700'. Lay			
down tubing to 4310' and pump 50 sxs cement and pump. Follow by 24 bbls of fresh water. COOH with tubing and wait 24			
hrs. GIH with tubing open ended and tag up @ 4190'. COOH laying down tubing to 1610'. Spot 50 sxs cement followed by 9 bbls of flush. COOH laying down tubing to 473'. Pump 50 sxs cement and follow with 2.5 bbls flush. COOH with tubing			
and wait 24 hrs. GIH with tubing and tag @ 370'. Lay down tubing and pump 10 sxs cement on surface. RD pulling unit			
and cut off wellhead. Install dryhole marker. Move equipment off of location. Cut off rig anchors. Clean and rake location			
for final inspection.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	TITLE	AGENT	DATE_9-6-03
Type or print name Devin Garner	E-mail address: Garner	oil@Yahoo.com	Telephone No. (505) 631-4770
ADDDD OVED BY) 1) 1 1 TITLE		DATE OCT 0 8 2003
APPPROVED BY Augustian TITLE DATE OCT 0 8 2003 Conditions of approval, if any			
· · · · · · · · · · · · · · · · · · ·			