



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**  
Governor  
**Joanna Prukop**  
Cabinet Secretary

**Mark E. Fesmire, P.E.**  
Director  
**Oil Conservation Division**

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

12-Feb-09

**DYAD PETROLEUM COMPANY**  
505 N BIG SPRING  
MIDLAND TX 79701

## LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.


Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

NEW MEXICO BO STATE No.004				P-12-18S-34E	30-025-02321-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/12/2009	Plugged Well Surface Restor	Maxey Brown	Yes	No	5/18/2009	iMGB0904351662
<b>Comments on Inspection:</b> DO NOT RELEASE. RULE 202. WELL IS P/A'D. MARKER OK. FLOWLINE STILL IN PLACE, CONDUIT FOR ELECTRIC MOTOR HAS NOT BEEN REMOVED, T/B ON LOCATION 3 TANKS, HEATER TREATER, CIRC PUMP. MISC JUNK. PIT CLOSED. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.						
NEW MEXICO BO STATE No.006				O-12-18S-34E	30-025-20005-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/12/2009	Plugged Well Surface Restor	Maxey Brown	Yes	No	5/18/2009	iMGB0904352825
<b>Comments on Inspection:</b> DO NOT RELEASE. RULE 202. MARKER HAS UL -P, SHOULD READ UL-O. NEED TO REMOVE FLOWLINE, ELEC CONDUIT, SHORT PIECE OF CSG CUT-OFF FROM EASTSIDE OF LOCATION AND ANY MISC JUNK. PIT IS CLOSE. THIS IS 1ST LETTER OF NON-COMPLIANCE.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




**COMPLIANCE OFFICER**

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER 017H15554612  
\$0.420  
02/12/2009  
Mailed From 88240

US POSTAGE

DYAD PETROLEUM COMPANY  
505 N BIG SPRING  
MIDLAND TX 79701