

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5c. Indicate Type of Lease
State Fee

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEAT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

Name of Operator
MURPHY OPERATING CORPORATION

Address of Operator
P. O. Drawer 2648, Roswell, New Mexico 88201

Location of Well
UNIT LETTER 10, 1650 FEET FROM THE East LINE AND 330 FEET FROM THE South LINE, SECTION 15 TOWNSHIP 12 South RANGE 32 East N.M.P.M.

7. Unit Agreement Name
Northeast Caprock Queen Unit

8. Farm or Lease Name
Northeast Caprock Queen Unit

9. Well No.
11

10. Field and Pool, or Wildcat
Caprock Queen

15. Elevation (Show whether DF, RT, GR, etc.)
4350.7' G.L.

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

REPAIR OR ALTER CASING

OTHER return to production

PLUG AND ABANDON

CHANGE PLANS

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOBS

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-86 Propose to clean out well to original T.D. @ 3016', run core bbl. & core from 3016' - 3036', run 2-3/8" tbg., 7/8" and 3/4" rods, 1-3/4" tbg. pump and return to production. Will evaluate to determine if stimulation is necessary, if so, then will acidize and/or frac for optimum production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED BY Lois N. Brown TITLE Production Clerk DATE July 11, 1986

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE _____ DATE JUL 13 1986

RECEIVED
JUL 14 1986
C. C. C.
HOBBBS OFFICE