

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
E-732X

7. Unit Agreement Name

8. Farm or Lease Name  
Anderson-State

9. Well No.

10. Field and Pool, or Wildcat  
Inbe Penn

12. County  
Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER-

2. Name of Operator  
Amini Oil Corporation

3. Address of Operator  
400 Wall Towers West; Midland, Texas 79701

4. Location of Well  
UNIT LETTER B, 1980 FEET FROM THE East LINE AND 660 FEET FROM  
THE North LINE, SECTION 35 TOWNSHIP 10-S RANGE 33-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
4204 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Plugging Procedure:
- No. 1 Set 30 sk plug @9710' and fill hole w/9.5 laden fluid, perms. @ 9734'-9747'.
  - No. 2 Top of cement behind 4-1/2" casing @8800'.
  - No. 3 Pull 4-1/2" casing from 7000'.
  - No. 4 Set 25 sk plug on top 4-1/2" casing stub.
  - No. 5 Set 25 sk plug on top of Glorieta @5310'.
  - No. 6 Set 50 sk plug @4220' in bottom of 8-5/8" csg.
  - No. 7 Pull 8-5/8" from 1400' set 25 sk plug at stub.
  - No. 8 Set 25 sk plug at base of surface @320'.
  - No. 9 Set 10 sk plug in top of 13-3/8" casing, set marker & clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kerian Gudwin TITLE Agent DATE 12-31-71

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT 4 DATE JAN - 3 1972

CONDITIONS OF APPROVAL, IF ANY: