

Supplemental Page #1
Forest Oil Corporation, Federal Warren #3
Subsequent Report of Abandonment

This well was plugged on April 23, 1951, in the following manner:

Halliburton Oil Well Cementing Co. pump spotted 50 sacks of cement from 974 up to 9582 -162' plug-through open end drill pipe.

Hole was mudded with 10.1#/gal. mud from 9582 to 4247'.

From 4247' in open 7 7/8" hole to 4167' in 8 5/8" OD intermediate casing a 25 sack cement plug was spotted through open end drill pipe.

The hole from 4167' to 4000' was mudded with 10.1#/gal mud.

A 4000' Baker Model "K" cast iron retainer bridging plug was set with a strain of 26,000#.

From 399' to 3949' a 48' plug of 15 sacks cement was spotted through Baker retainer setting tool.

From 349' to 32' the hole was filled with 10.1#/gal mud.

From 32' to surface a 10 sack cement plug was placed.

On top of the 8 5/8" OD casing was installed a swedge nipple (8" OD X 2") on top of which was placed a 2" 2000# W.O.G. plug valve.

In top of the plug valve is a swedge nipple into which is filed a 1 1/2" OD permanent metal marker closed on top which is 4 feet above ground level and which is painted aluminum. Attached are duplicate copies of electric logs to total depth by Schlumberger Well Surveying Corporation.

of the...
report...
relates...

...
...

...
...
...

...
...
...

...
...
...

...
...
...

...
...
...

...
...
...
...
...