DISTRIBUTION			
			Form C-103 Supersedes Old
	_		C-102 and G-103
SANTAFE	NEW MEXICO OIL CONS	SERVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.		*	5a. Indicate Type of Lease
LAND OFFICE	_		State X Fec.
OPERATOR			5. State Oil & Gas Lease No.
			K-3836
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			
1.	THE TEN TEN TEN TEN TEN TEN TEN TEN TEN TE	A PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL 2. Name of Operator	OTHER•		
2. Name of Operator			8, Farm of Lease Name
Charles B. R	Read		Shell-State
3. Address of Operator			9. Well No.
P. O. Box 21	126, Roswell, New Mexic	co 88201	1
4. Location of Well			10. Field and Pool, or Wildeat
UNIT LETTERA,	660 FEET FROM THE North	LINE AND 510 PEET PRO	(undesignated Penn) North-Bagley
•			HHIHHHHH
THE <u>Last</u> Line, sect	10N 18 TOWNSHIP 1		
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	4308.6 Gro	ound	Lea (IIIIIIII
Check	Appropriate Box To Indicate N		
NOTICE OF I	INTENTION TO:		
1101102 01 1	THE PROPERTY OF	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK			
Ħ	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
17 Describe Described			
work) SEE RULE 1103.	operations (Clearly state all pertinent deta	rils, and give pertinent dates, includin	g estimated date of starting any proposed
Comm	nence drilling operations	12:00 noon 1-24-68	Sat 4101 of
Comr 38# 12 3/4" c	nence drilling operations	12:00 noon 1-24-68.	Set 410' of
38# 12 3/4" c	asing with 350 sacks of a	ement. Plug down 9:4	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs.	asing with 350 sacks of a Tested 1,000 lbs., pres	sement. Plug down 9:4 sure held. Set 3770'of	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs.	asing with 350 sacks of a Tested 1,000 lbs., pres	sement. Plug down 9:4 sure held. Set 3770'of	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sement. Plug down 9:4 sure held. Set 3770'of g down 3:45 p.m. 1-28	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plu	sure held. Set 3770'of sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68. 32#, 28# and 24# -68. WOC 18 hrs.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68. 32#, 28# and 24# -68. WOC 18 hrs.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 3: Tested casing	asing with 350 sacks of a Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressu	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68. 32#, 28# and 24# -68. WOC 18 hrs.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39 Tested casing	asing with 350 sacks of of Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressure above is true and complete to the best of title.	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68. 32#, 28# and 24# -68. WOC 18 hrs.
38# 12 3/4" c WOC 18 hrs. 8 5/8" with 39 Tested casing	asing with 350 sacks of of Tested 1,000 lbs., pres 50 sacks of cement. Plug with 1,000 lbs., pressure above is true and complete to the best of title.	sure held. Set 3770'of g down 3:45 p.m. 1-28 are held.	5 p.m. 1-24-68. 32#, 28# and 24# -68. WOC 18 hrs.