SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Supersedes Old C-102 and C-103 Effective 1-1-65
FUE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-03
U.S.G.S.	_	5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		0G 5791
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL V GAS		7. Unit Agreement Name
well \(\Delta\) well \(\Delta\)	OTHER-	8. Farm or Lease Name
Cayman Corporation 3. Address of Operator		9. Well No.
	, Midland, Texas 79701	2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE South LINE AND 1980	FEET FROM Vada Penn
- .	7 100 045	
THE East LINE, SEC	ction 7 township 10\$ range 34E	NMPM: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4210.8 GR	Lea
16. Chec	k Appropriate Box To Indicate Nature of Notice, Repo	ort or Other Data
		SEQUENT REPORT OF:
	רסח	<u></u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JO	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	** L_J
OTHER		
OTHER		in Italian estimated data of starting any proposed
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates	
17. Describe Proposed or Completed work) SEE RULE 1103. As soon as a riwell by perform (1) Cu (2) Pl (3) Cu (4) Pl (5) Pl (6) Pl	ig is available it is the intention of operming the following operations: ut and recover approximately 3700' of 5-1/2 ut of hole. 8-5/8" csg. set at 3982'. lace a 100 sx cmt. plug at top of 5-1/2" cs ut and recover as much 8-5/8" csg. as possi lace a 55 sx cmt. plug at top of 8-5/8" csg lace a 75 sx cmt. plug at base of 13-3/3" c lace a 10 sx cmt. plug at surface.	ator to plug and abandon this " csg. Unable to fish tbg. g. stub. ble stub. sg. at 354'.
17. Describe Proposed or Completed work) SEE RULE 1103. As soon as a riwell by perform (1) Cu (2) Pi (3) Cu (4) Pi (5) Pi (6) Pi (7) Pi Series	ig is available it is the intention of operming the following operations: ut and recover approximately 3700' of 5-1/2 ut of hole. 8-5/8" csg. set at 3982'. lace a 100 sx cmt. plug at top of 5-1/2" csut and recover as much 8-5/8" csg. as possilace a 55 sx cmt. plug at top of 8-5/8" csg. lace a 75 sx cmt. plug at base of 13-3/3" clace a 10 sx cmt. plug at surface. lace a marker as required by State regulation of the second of the	ator to plug and abandon this " csg. Unable to fish tbg. g. stub. ble stub. sg. at 354'.
17. Describe Proposed or Completed work) SEE RULE 1103. As soon as a riwell by perform (1) Cu (2) Pi (3) Cu (4) Pi (5) Pi (6) Pi (7) Pi Series	ig is available it is the intention of operming the following operations: ut and recover approximately 3700' of 5-1/2 ut of hole. 8-5/8" csg. set at 3982'. lace a 100 sx cmt. plug at top of 5-1/2" csut and recover as much 8-5/8" csg. as possilace a 55 sx cmt. plug at top of 8-5/8" csg. lace a 75 sx cmt. plug at base of 13-3/8" csg. lace a 10 sx cmt. plug at surface. lace a marker as required by State regulation of the state	ator to plug and abandon this " csg. Unable to fish tbg. g. stub. ble. stub. sg. at 354'. ons. a Spossible to fish tbg. a COMMISSION MUST SE NOTISED 24 burs frich to the bleshing of Jeging operations for the C-103 BE APPROVED.
17. Describe Proposed or Completed work) SEE RULE 1103. As soon as a riwell by perform (1) Cu (2) Pi (3) Cu (4) Pi (5) Pi (6) Pi (7) Pi Series	ig is available it is the intention of operming the following operations: ut and recover approximately 3700' of 5-1/2 ut of hole. 8-5/8" csg. set at 3982'. lace a 100 sx cmt. plug at top of 5-1/2" csut and recover as much 8-5/8" csg. as possilace a 55 sx cmt. plug at top of 8-5/8" csg. lace a 75 sx cmt. plug at base of 13-3/3" clace a 10 sx cmt. plug at surface. lace a marker as required by State regulation of the second of the	ator to plug and abandon this " csg. Unable to fish tbg. g. stub. ble stub. sg. at 354'. ons. Z COMMISSION MUST ST MOTIFED 24 DURS FRICK TO THE DECIMING OF JOGSING OPERATIONS FOR THE C-103
17. Describe Proposed or Completed work) SEE RULE 1103. As soon as a riwell by perform (1) Cu (2) Pl (3) Cu (4) Pl (5) Pl (6) Pl (7) Pl (7) Pl	ig is available it is the intention of operming the following operations: ut and recover approximately 3700' of 5-1/2 ut of hole. 8-5/8" csg. set at 3982'. lace a 100 sx cmt. plug at top of 5-1/2" csut and recover as much 8-5/8" csg. as possilace a 55 sx cmt. plug at top of 8-5/8" csg lace a 75 sx cmt. plug at base of 13-3/3" clace a 10 sx cmt. plug at surface. lace a marker as required by State regulation of the state of the state regulation of the state of the st	ator to plug and abandon this " csg. Unable to fish tbg. g. stub. ble. stub. sg. at 354'. ons. a spossible to fish tbg. a commission must be worked 24 ours frior to the planting of Jeging operations for the cities approved. Be approved.