

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Midwest Oil Corporation	8. Farm or Lease Name Cross "A"
3. Address of Operator 1500 Wilco Bldg. Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4287 GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-5-74 Plugged & abandoned as follows;
Set 5 1/2" CIBP @ 9620 w/ 4 sx cmt from 9620' to 9585'
5 1/2" casing shot & recovered from 6734'.
Ran tbg. and set 40 sx cmt plug from 6675' to 6675'
Ran tbg. and set 40 sx cmt plug from 5400' to 5300'
Ran tbg. and set 50 sx cmt plug from 3995' to 3895'
8 5/8" csg shot @ 1225' & 1025' - Recovered from 1025'/
Ran tbg. and set 55 sx cmt plug from 1075' to 975'
Ran tbg. and set 75 sx cmt plug from 370' to 270'
Ran tbg. and set 10 sx cmt plug from 15' to surface

Installed dry hole marker
Hole was circulated w/ and all cement plugs set w/ brine mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alvin Milford TITLE Agent DATE 1-28-74

APPROVED BY _____ TITLE _____ DATE AUG 28 1975

CONDITIONS OF APPROVAL, IF ANY: