Gas gravity		Oil gravity					
				URING DEVICE US			
Date Time	a.m.	Choke Size	Surface Pressure psi	Gas Rote MCF	Liquid Rate BPD	Remarks	
6:00						Tester on location	
9:30						unloaded and made up tools	
11:00						Started tools in hole	
1:45 A		Bubble Hose				Opened tool with a weak blow	
2:00		TF.				Closed tool with a blow	
3:02		п				Opened tool with no blow	
4:02						Closed tool with no blow	
6:03						Jarred loose	
6:24						Loose, started out of hole	
10:15						Out of hole, laid down tools and	
						read sampler	
						Loaded out	
						Job complete	
					·		
		+	7		· · · · · · · · · · · · · · · · · · ·		