

COPIES RECEIVED		
DISTRIBUTION		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**B-8318**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection</b>	7. Well Agreement Name <b>North Caprock Queen Unit 2</b>
2. Name of Operator <b>Anadarko Production Company</b>	8. Farm or Lease Name <b>Tract #29</b>
3. Address of Operator <b>P. O. Box 647 Artesia, New Mexico 88210</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>36</b> TOWNSHIP <b>12S</b> RANGE <b>31 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Caprock Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4405 GL</b>	12. County <b>Chaves</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Pumped 25 sacks cement at 3003'. Cut off oil string at 940. Pumped 25 sacks cement at casing cut off point. pumped 25 sacks cement at base of surface casing. Ten sacks at surface with heavy mud between all plugs. Set surface marker and cleaned up location.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. D. Muncy, Jr. TITLE Agent DATE 5/16/74  
 APPROVED BY Shirley W. Kingman TITLE Geologist DATE DEC 7 1974  
 CONDITIONS OF APPROVAL, IF ANY: