

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
V-1232

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- Dry

2. Name of Operator
Manzano Oil Corporation 505/623-1996

3. Address of Operator
P.O. Box 571/Roswell, NM 88202

4. Location of Well
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 36 TOWNSHIP 8-S RANGE 32-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

7. Unit Agreement Name

8. Farm or Lease Name
Sunburst 36 State

9. Well No.
1

10. Field and Pool, or Wildcat
Undesignated Wildcat

12. County
Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/22/85 Shoot casing off at 2921'. Pull and lay down 69 joints (2921') of 5½" casing. Plugged and abandoned well as follows: Set cast iron bridge plug @ 4262'. Set 100' plug with 20 sacks Class H 50' in 5½" casing and 50' in 8-5/8" casing, waited 3 hours. Tagged plug at 2880', 41' of cement above cut off @ 2921'. Pulled up and set 100' plug at 1760' to 1660' with 30 sacks Class H. Pull out of hole and set 10' surface plug. Set dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jackie Midkiff TITLE Jackie Midkiff/Prod. Clerk DATE 2/6/86

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JAN 2 1987

CONDITIONS OF APPROVAL, IF ANY:

E