

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. MM-01124
2. NAME OF OPERATOR Shelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME ---
3. ADDRESS OF OPERATOR P. O. Box 1351, Midland, Texas 79701		7. UNIT AGREEMENT NAME ---
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FWL and 1650' FWL, Sec. 35-138-33E		8. FARM OR LEASE NAME Willard Beatty
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Lazy "J" Pool
		11. SEC., T., R., E., M., OR BLM. AND SURVEY OR AREA Sec. 35-138-33E
		12. COUNTY OR PARISH Leon
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) Open additional and stimulate ☒		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well is presently producing from the Bough formation through 5-1/2" OD casing perforations 9705-9783'. We propose adding perforations and stimulating old and new perforations as follows:

- 1) Move in workover rig and pull tubing and packer.
- 2) Perforate 5-1/2" OD casing with one shot per place as follows: 9643', 9648', 9658', 9665', 9676', 9686', 9690', 9694', 9698', 9741', and 9755'.
- 3) Set packer at 9735' and bridge plug at 9765'.
- 4) Treat perforations 9741' and 9755' with 500 gallons 15% NE acid.
- 5) Set bridge plug at 9705' and packer at 9620' and treat perforations 9643-9698' with 1500 gallons 15% NE acid and 14 ball sealers.
- 6) Release bridge plug, set packer and treat all perforations with 6,000 gallons chemically-retarded acid in two stages with a 500-lb. Benzoic acid flake block between stages.
- 7) Swab and test.
- 8) Pull tubing, packer and bridge plug.
- 9) Return tubing and pumping equipment and return well to production status.

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) D. R. Crow TITLE Lead Clerk DATE Dec. 16, 1971

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and is approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; and or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983 O-685229

R47-485