

NO. COPIES RECEIVED			
DISTRIBUTION			
OFFICE			
FOR			

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-9641

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.

1. Well <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Unit Agreement Name
3. Name of Operator	4. Farm or Lease Name
Atlantic Richfield Company	State R
5. Address of Operator	6. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	2
7. Location of Well	8. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	Saunders
THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.	
9. Elevation (Show whether DF, RT, GR, etc.)	10. County
4206' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 3/30/75 rigged up, installed BOP. Ran bit & scraper to 9500'. Ran CIBP on WL & set @ 9500'. WIH w/tbg to top of BP, spotted 50 sk cmt plug on top of BP @ 9500'. Circ hole w/9# mud. 5 1/2" csg was indicated to be free @ 6400'. Cut 5 1/2" csg @ 6400'. Unable to pull. Cut @ 6000', unable to pull. Shot off csg @ 5083' & recovered. Spotted 25 sk cmt plug 5460-5670' across top Glorieta. Spotted 40 sk cmt plug 5008-5150' across 5 1/2" csg stub. Spotted 50 sk cmt plug 4018-4226' across 8-5/8" csg shoe. Spotted 50 sk cmt plug 1492-1625' @ top of salt. Spotted 10 sk cmt plug @ surface. Installed regulation dry hole marker. P&A eff 4/4/75. Final Report.

Note: Your office to be notified when location is cleaned & levelled for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED John W. Remy
APPROVED BY John W. Remy
CONDITIONS OF APPROVAL, IF ANY:

Dist. Drlg. Supv.

4/10/75

TITLE

DATE