Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Departmen

Form C-103 Revised 1-1-89

DISTRICT I	Energy, Minerals and Natural Resources Department	Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	P.O. Box 2088 Santa Fe, New Mexico 87504-2088	30-025-01176
DISTRICT III		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELLS	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
(DO NOT USE THIS FORM FOR PRO	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT HESEF	RVOIR. USE "APPLICATION FOR PERMIT" -101) FOR SUCH PROPOSALS.)	7. Lease Name of Unit Agreement Name
I. Type of Well:		1
WELL XX WELL 2. Name of Operator	omes	Stevens
Charles B. Gillespie, J	Jr.	8. Well No.
3. Address of Operator		9. Pool name or Wildcat
P. O. BOX 8 Meli Location	Midland, Texas 79702	Saunders Permo Upper Penn
Unit LetterP : 660	Feet From The South Line and 66	O Feet From The East Line
		Feet From The Last Line
Section 33	Township 14S Range 33E 10. Elevation (Show whather DF, RKB, RT, GR, etc.)	NMPM Lea County
	4197 DF	
1. Check A	Appropriate Box to Indicate Nature of Notice, R	eport or Other Data
NOTICE OF INT		SEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
EMPORARILY ABANDON		ALTERING CASING
JLL OR ALTER CASING	CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT XX
	CASING TEST AND CE	MENT JOB
THER:	OTHER:	
 Describe Proposed or Completed Operations of the North SEE RULE 1103. 	cos (Clearly state all pertinent details, and give pertinent dottes, inclu	ding estimated date of starting any proposed
	ulled 5 1/2" casing from 4931'.	
1/15/91: Mixed and pum	ped 25 \$X cement at 4960' across 5 1	/2" casing stub.
1/16/91: Tagged plug a	t 4880'. Mixed and pumped 35 SX cem	ent at 42ŎO'. Tagged plug
at 4040'.	ulled 9 5/9" casing from 406!	
1/17/91: Cut off and pe	ulled 8 5/8" casing from 496'. ped 60 SX cement at 545' across 8 5/8	3" casing stub.
1/17/91: Cut off and p 1/18/91: Mixed and pum 1/21/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen	at 346'.
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a 4" marker to	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen surface pipe, cleaned location.	at 346'.
1/17/91: Cut off and pum 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a 4" marker to	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemens surface pipe, cleaned location.	at 346'. nt at surface. Welded
1/17/91: Cut off and pull 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a 4" marker to	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemen surface pipe, cleaned location.	at 346'. nt at surface. Welded
1/17/91: Cut off and pum 1/18/91: Mixed and pum 1/21/91: Tagged plug a 1/22/91: Tagged plug a 4" marker to	ped 60 SX cement at 545' across 8 5/8 t 455'. Mixed and pump 80 SX cement t 241'. Mixed and pumped 10 SX cemens surface pipe, cleaned location.	at 346'. nt at surface. Welded

RN

CONDITIONS OF APPROVAL, IF ANY: