NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS 10:43

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is comp r iı

instructions in the Rules and Regulatio	Indicate Nature of Rep	port by Checking B	elow	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESU OF CASING SHUT		REPORT ON REPAIRING W	VELL
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECO	OMPLETION	REPORT ON (Other)	
	May	3, 1955	Hob)	hs, New Mexico
Following is a report on the wor				
Stanolind Oil and (Company or O	Gas Company	·····	Lois Wing	gerd
Cactus Drilling Co	mpany	, Well No 12	in the SW	SE 1/4 of Sec24,
T 12-S., R 37-E., NMPM.,	ladiola	Pool,	Lea	County.
The Dates of this work were as follows:	May 1. 1955 t	o May 3. 1	.955	
	_			10
Notice of intention to do the work	(was not) submitted on Form	n C-102 on	(Cross out incorrect wor	ds)
Notice of intention to do the work and approval of the proposed plan		m C-102 on	(Cross out incorrect wor	ds)
DETA	(was not) obtained. HED ACCOUNT OF WORK	DONE AND RES	oults obtained ing set at 45	00° with
on May 1, 1955, staging tool set 440 sacks mixed neat. After WO	We ran 4487' of at 2312'. Ceme 8% gel plus 100 c for 30 hours, t and 30 minutes. Ning with 1000 psi	DONE AND RES 5-1/2" casi nted in two sacks neat; ested casi	ing set at 45 o stages; 1st c 2nd Stage: ng before dri	00° with Stage: 150 sacks lling plug ter drilling
On May 1, 1955, staging tool set 440 sacks mixed neat. After WOO with 1000 psi for plug tested cas: Resumed operation. Witnessed by C. D. Harve (Name	Hed Account of Work we ran 4487 of at 2312. Ceme 8% gel plus 100 for 30 hours, tor 30 minutes. Ning with 1000 psions.	bone and Res 5-1/2* casi nted in two sacks neat; ested casi o drop in p for 30 min	ing set at 45 o stages; 1st c 2nd Stage: ig before dri pressure. Af nutes. No dro	OO! with Stage: 150 sacks lling plug ter drilling p in pressure. Hd. Rsbt.
On May 1, 1955, staging tool set 440 sacks mixed neat. After WOO with 1000 psi fe plug tested cas: Resumed operation.	Hed Account of Work we ran 4487 of at 2312. Ceme 8% gel plus 100 for 30 hours, tor 30 minutes. Ning with 1000 psions.	to bone and Res 5-1/2* casi nted in two sacks neat; ested casis o drop in second of the sacks neat; for 30 min (Company) I hereby certify to the best of m	ing set at 45 stages; 1st stages; 1st gefore dripressure. Af nutes. No dro Gas Company that the information gives you knowledge. Original Signed by	OO! with Stage: 150 sacks lling plug ter drilling p in pressure. Hd. Rsbt. (Title) en above is true and complete
On May 1, 1955, staging tool set 440 sacks mixed neat. After WOO with 1000 psi for plug tested cas: Resumed operation. Witnessed by C. D. Harve (Name	(was not) obtained. HED ACCOUNT OF WORK We ran 4487' of at 2312'. Ceme 8% gel plus 100 for 30 hours, to or 30 minutes. No long with 1000 psi ons. Stanoling COMMISSION	d Oil and (Company) I hereby certify to the best of m Name	ing set at 450 stages; 1st; 2nd Stages; 1st; 2nd Stages; 1st; 2nd Stage; ag before dripressure. Af nutes. No dro that the information gives knowledge. Original Signed by MPH L. HENDRICKSON	OO! with Stage: 150 sacks lling plug ter drilling p in pressure. Hd. Rsbt. (Title) en above is true and complete

,	T Company of the comp
	*
	I to the second
·	
	Rec