

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-8176	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Cabot Petroleum Corporation		8. Farm or Lease Name New Mexico 'C' State	
3. Address of Operator P. O. Box 5001, Pampa, TX 79065		9. Well No. 1	
4. Location of Well UNIT LETTER E 2310 FEET FROM THE North LINE AND 330 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 13S RANGE 37E N.M.P.M.		10. Field and Pool, or Wildcat King Devonian	
15. Elevation (Show whether DF, RT, GR, etc.) 3854 D.F.		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 6/21/85 RIH and shot total of 46 shots from 12,150'-12,240' w/3 1/4" Hornets Nest Strip. Acidized w/3000 gal. 20% CRA acid w/salt block. Made 11 swab runs. On 6/25/85 GIH w/4" perf. gun & shot 4 holes at 4630'. Spot 2 sxs sand on top of RBP @ 9615' and pumped 200 sxs Halliburton Class C Neat cement down 5 1/2" csg, circ. up 8 5/8" csg w/rubber cmt. plug on top. Pumped plug to approx. 4530'. Close in 8 5/8" and 5 1/2" w/650#. Drilling rubber plug and cement @ 4521' and drilled thru at 4690'. Press. up on 5 1/2" csg to 600#. Circ. sand off RBP and release RBP. Run Reda pump, bottom set @ 9684'. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter J. Miner TITLE Agent DATE 8/27/85

ORIGINAL SIGNED BY JOHN SEXTON

APPROVED BY JOHN SEXTON TITLE DATE AUG 30 1985

CONDITIONS OF APPROVAL, IF ANY:

1000000000

1000000000

1000000000