Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within the days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of easing hut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional

instructions in the Rules and Regulation	ns of the Commission.			
	Indicate Nature of Repo	rt by Checking Below	<b>w</b>	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESUL OF CASING SHUT-C		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECON	(PLETION	REPORT ON (Other)	
	Desamb	er 22, 1952	Hebbs, No.	Maxi oo
Following is a report on the work	done and the results obtained u	inder the heading not	ted above at the	
Gulf Oil Corporation	mara(ar)	Les State MAYN (Lesse)		
Western Drilling Comp				
т 12-9., к 38-Е., нмрм.,	<u> </u>	Pool,	Lea	Count
The Dates of this work were as follows:	December 18 - 20	1952		
Notice of intention to do the work (323)	(was not) submitted on Form (	Z-102 on		19
and approval of the proposed plan (		(C	ross out incorrect words)	
DETA	ILED ACCOUNT OF WORK D	ONE AND RESULI	rs obtained	
	13-3/8" OD 8 RT R-2 / lar Lonestar Portland oximately 20 sacks cen	cement. Plug		
below casing shoe w/4	pressure. Drilled sem 00# pressure for 30 m	ent plug from Lnutes. There	360° to 385°, tested was no drop in pres	d coment sure.
After approval of Mr. made to drill ahead.	Yarbrough, State Oil	and Gas Inspe	etor, preparations	roro
		on or	DEC 31 1825	<u>م</u>
Witnessed by		Corporation	Devilling Forem	un
Approved: OIL CONSERVATION	COMMISSION	I hereby certify that to the best of my kno	the information given above is t	rue and complet
Var makers	uh	Name Name	an Jay	8
(Namb)		` ·	es Prod. Supt.	
U Gas Inspector	DEC 20 Hada		lf Oil Corporation	
(Title)	(Date)	AddressBR	x 21.67, Hobbs , Menc. 1	<b>277</b> 00