## State 01 New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION P.O. Box 2088 P.O. Box 2088	wrighth 29-07208
Santa Fe, New Mexico 87504-2088 O. Downer DD, Artesia, NM 88210	5. indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brance Rd., Astec, NM 87410	6. State Oil & Gas Leese No. LG-0043
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT, USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM 0-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
Type of Well: OL OAS WILL C OTHER	Brian State
. 'Name of Operator	8. Weil No.
ELK OIL COMPANY  Address of Operator	9. Pool same or Wildest
P. O. Box 310 Roswell, N.M. 88202	Gladiola Devonian
Unit Lower A: 330 Feet Prom The North Line and 990  Section 19 Township 12 South Range 38 East  10. Blevation (Show whether DF, RKB, RT, GR, etc.)	Tea
Check Appropriate Box to Indicate Nature of Notice, F	
	BSEQUENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	L ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS   COMMENCE DRILLIN	NG OPNS. L. PLUG AND ABANDONMENT 🔀
	( <del></del> )
CASING TEST AND C	[-]
CASING TEST AND COTHER:	CEMENT JOB
ULL OR ALTER CABING CASING TEST AND COTHER:	CEMENT JOB
CASING TEST AND CONTINUES:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, increase) SEE RULE 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag	CEMENT JOB
CASING TEST AND CONTINUEN:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud	CEMENT JOB
CASING TEST AND CONTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomed.) SEE RULE 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud Install Dry Hole Marker  Location cleaned, leveled and ready for inspection.	CEMENT JOB
CASING TEST AND COTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incored) SEE RULB 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud Install Dry Hole Marker	cluding estimated date of starting any proposed
CASING TEST AND COTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incovern) SER RULB 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud Install Dry Hole Marker  Location cleaned, leveled and ready for inspection.    Descript and the information shows is true and complete to the best of my knowledge and balled.	cluding estimated date of starting any proposed  dent
CASING TEST AND CONTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc. work) SEE RULE 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud Install Dry Hole Marker  Location cleaned, leveled and ready for inspection.    1   Describe Proposed or Complete to the best of my knowledge and belief.	cluding estimated date of starting any proposed
CASING TEST AND COTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc. work) SEE RULE 1103.  6-10-94 Spot 200 sxs @ 6336'-6321 and tag 6-14-94 Perf. @ 4642' and squeeze 50 sxs tag @ 4530' 6-15-94 Spot 60 sxs @ 3050'-2871' and tag 6-16-94 Spot 60 sxs @ 1050'-989' and tag 6-16-94 Spot 60 sxs @ 400'-292' and tag 6-16-94 Spot 10 sxs @ surface  Circulate hole with 10# mud Install Dry Hole Marker  Location cleaned, leveled and ready for inspection.  President and the information down in two and complete to the best of my knowledge and belief.  President and the second and tag.	cluding estimated date of starting any proposed  DATE May 2, 1996  TELEPHONE NO. 505623-3

Recolved Only