

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
Other instructions
on the inside

FE*

Form approved.
Bureau Form No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

LC-064605

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Amerada Hess Corporation		8. FARM OR LEASE NAME Federal "B"
3. ADDRESS OF OPERATOR Drawer D, Monument, New Mexico 88265		9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1983' ENL & 549' FEL		10. FIELD AND FOOL, OR WILDCAT Bronco Siluro-Devonian
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T13S, R38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3810' DF		12. COUNTY OR PARISH: 13. STATE Lea N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*

(Other) Squeeze & re-perforate X

(Note: Report results of multiple completion on Well Completion or Reconception Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to pull tbg. & hydraulic pumping equipment, run 4-5/8" bit and check fill inside 5-1/2" liner, run retrievable bridge plug and pkr. and test 5-1/2" liner & 7" csg. as necessary, run cement retainer and set in 5-1/2" liner at 11,725' & squeeze Devonian zone thru 5-1/2" liner perf. fr. 11,741' to 11,782' w/200 sks. Class H cement with additives, check top of cement inside 5-1/2" liner and perforate 5-1/2" liner opposite Devonian zone from 11,695' to 11,715' with two shots per foot, acidize Devonian zone thru 5-1/2" liner perf. fr. 11,695' to 11,715' with 1000 gal. 15% HCl NE FE acid using diverter, swab load, re-run hydraulic pumping equipment on 2-3/8" tbg. and resume production.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>E. B. Fisher</u>	TITLE <u>Supv. Adm. Ser.</u>	DATE <u>9-17-84</u>
ACCEPTED FOR RECORD (This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE	DATE
CONDITIONS OF APPROVAL <u>SEP 21 1984</u>		

Chickland NEW MEXICO

*See Instructions on Reverse Side