

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20468

5. Indicate Type of Lease STATE [X] FEE []

6. State Oil & Gas Lease No. V-1518

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name Texas Crude AHL State

1. Type of Well: OIL WELL [] GAS WELL [] OTHER P&A WELL [X] Re-entry

8. Well No. 1

2. Name of Operator YATES PETROLEUM CORPORATION 25575

9. Pool name or Wildcat High Plains Permo Penn 3055

3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 27 Township 14S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4100' (top tubinghead)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] OTHER: [] SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [] PLUG AND ABANDONMENT [X] CASING TEST AND CEMENT JOB [] OTHER: []

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-17-93. P&A well as follows: Set CIBP at 10360', cap w/35' cement. Set CIBP at 9620', cap w/35' cement. Ran free point on 5-1/2" casing, free point at 8500'. Ran tubing to 9620' (top of CIBP). POH w/tubing. WIH and cut 5-1/2" casing at 8610'. Laid down 102 joints 5-1/2" casing. RU casing jacks. Pulled 280,000# - unable to pull up inside 7". RD casing jacks and equipment. RU tubing equipment. Ran tubing to 8665', spot 35 sx cement plug at 5-1/2" casing stub. Pull 25 stand. SI. WOC. Tag cement plug at 8573'. Pull tubing to 7430', spot 35 sx cement. Pull up to 5750', spot 35 sx cement. Pull and stood back 4600' tubing. Laid down extra tubing. RU wireline and 5-1/2" jet cutter. Ran 4410' and cut 5-1/2" casing. Unable to work casing free. RIH to 4286', cut pipe. RU casing jacks. Pull and laid down 5-1/2" casing. RU tubing equipment. Ran tubing to 4608', spot 60 sx cement plug. WOC. Tag plug at 4385'. ND 7" wellhead. Weld on free pt pipe free at 2200'. RU 7" cutter. Cut casing at 2128' RU casing equipment. Laid down 52 joints 7" casing. Ran tubing to 2178' and spot 35 sx cement plug. Tag plug at 2058'. Pull tubing to 1535', spot 35 sx cement plug. RD tubing equipment and weld on to 9-5/8" casing. Cut 9-5/8" at 990'. Ran tubing to 1040'. Spot 70 sx cement plug. Tag plug @ 936'

I hereby certify that the information above is true and complete to the best of my knowledge and belief. (continued - page 2)

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-1-93 TELEPHONE NO. 505/748-1471

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE OCT 25 1993

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-20468
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1518

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name Texas Crude AHL State

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
--

8. Well No. 1

2. Name of Operator YATES PETROLEUM CORPORATION
--

9. Pool name or Wildcat High Plains Permo Penn

3. Address of Operator 105 South 4th St., Artesia, NM 88210
--

4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>14S</u> Range <u>34E</u> NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4100' (top tubinghead)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Page 2 - continued) Spotted cement plug 387', cemented w/85 sacks. Tagged plug at 282'.
Spotted 15 sx surface plug.
Install regulation abandonment marker.

WELL PLUGGED AND ABANDONED. WORK COMPLETED 3-27-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-1-93
 TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Jack Griffin TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: _____