

State of New Mexico  
Energy, Minerals and Natural Resources Department

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088Submit 3 Copies  
to Appropriate  
District OfficeDISTRICT I  
P.O. Box 1980, Hobbs, NM 88240DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-025-22111

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒GAS  
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

7. Lease Name or Unit Agreement Name

Childress AKV

8. Well No.

2

9. Pool name or Wildcat

Saunders Permian Upper Penn

4. Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section 1

Township 14S

Range 33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4196' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOB ☐OTHER: Re-entry ☒ALTERING CASING ☐PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-3-94 - Notified OCD in Hobbs of commencing operations.

8-4-94 - Cleaned pad. Welded on starting head. Installed spool and BOP. Moved in pulling unit.

8-5-94 - Rigged up pulling unit. Nippled up BOP. Picked up 10-3/4" mill tooth bit, 4-3/4" drill collars with swivel. Spudded at 11:00 AM 8-4-94. Drilled surface plug. Washed down to 11-3/4" shoe. Mix mud. Closed BOP. Could not get test on casing. No leaks on surface. Drilled shoe plug at 375'. Wash and ream tight spots.

8-6-94 - Drilling at 870'. Tag stub plug at 1190'. Drilled down to stub. Circulate and clean. TOOH. Put on 7-7/8" bit. TIH. Did not tag stub. Washed down to 1466'. Circulate clean. TOOH.

8-7-94 - TIH w/7-7/8" bit, 4-1/2" pilot sub, 10-1/2" OD dress off mill, bowen jars, 10 4-3/4" drill collars. Washed down from 1220' to stub. Cut 3'. Circulate clean. TOOH. TIH with 10-3/4" OD slip joints &amp; 29 joints 8-5/8" 32# casing. Tag stub. Rotate with tongs. Moved down 4'. Rotate casing with no torque. Indicates over stab. Nippled down BOP. Set slips.

Cut off 13-5/8" X 10" 900 spool. Nippled up BOP. TIH w/bit, drill collars &amp; tubing. Set down at splice. Rigged up swivel. Rotated 30 minutes. Could not get in pipe. TOOH.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 8-16-94TYPE OR PRINT NAME Rusty Klein505-748-1471  
TELEPHONE NO.

(This space for State Use)

APPROVED BY

TITLE

DATE

AUG 18 1994