

NO. OF COPIES RECEIVED		
DISTRIBUTION		
UNIT FEE		
STATE FEE		
S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
LG-1923

7. Unit Agreement Name

8. Farm or Lease Name
J.M.

9. Well No.
1

10. Field and Pool, or Wildcat
North Morton Permo Penn

12. County
Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL OR RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.")

OIL WELL GAS WELL OTHER

Name of Operator
ELK OIL COMPANY

Address of Operator
P. O. BOX 310, ROSWELL, NEW MEXICO 88201

Location of Well
UNIT LETTER **P** **660** FEET FROM THE **South** LINE AND **660** FEET FROM
THE **East** LINE, SECTION **26** TOWNSHIP **14S** RANGE **34E** NMPM.
15. Elevation (Show whether DF, RT, CR, etc.)
4085 Grd.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REWORK OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Elk Oil Company proposes to Plug and Abandon well as follows:

1. 50' plug @ 10,516 perforation.
2. Attempt to recover 8000' of pipe, 50 sx. plug in and out of 4 1/2" casing stub @ 8000'.
3. 50' plug @ 6000'.
4. 50 sx. plug @ base of 8 5/8" casing @ 4496'.
5. Attempt to pull 1500' of pipe, 100' plug inside and out of 8 5/8" casing stub @ 1500'.
6. 10' plug @ surface.
7. Standard 4' x 4' dry hole marker.
8. Mud between all plugs.

100' PLUG ACROSS SHOULDER OF SURFACE PIPE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Joseph J. Kelly

TITLE President

DATE 3/20/86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE

DATE **MAR 24 1986**

CONDITIONS OF APPROVAL, IF ANY: