

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3716	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <div>OIL WELL <input type="checkbox"/></div> <div>GAS WELL <input type="checkbox"/></div> <div>OTHER- P&amp;A</div>	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Midwest-Hightower ADS St.
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>12S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or WHdcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4305.4' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-86. Subsequent report of P&A.  
Set CIBP at 9400-9200' and spotted 25 sx Class H cement w/2% CaCl2. Tagged plug at 8650'.  
Cut 5½" casing at 8578' and attempted to pull, but would not come.  
Ran free point - 5½" stuck at 4700' and free at 4650'.  
  
Called Paul Kautz, NMOCD, Hobbs, NM and obtained verbal permission to amend plugging as follows:  
  
Spot 100' cement plug across cut at 8578'.  
Cut and pull 5½" casing from 4600'.  
Set cement plug 50' in and 50' out 5½" casing stub.  
  
Complete plugging as per our C-103 report submitted 3-17-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>Production Supervisor</u>	DATE <u>3-20-86</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT I SUPERVISOR</u>	TITLE _____	DATE <u>MAR 24 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED  
MAR 21 1986  
O.C.D.  
HOBBS OFFICE