

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26895
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4945

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name  Saunders 16 State
2. Name of Operator MWJ PRODUCING COMPANY	
3. Address of Operator 400 W. Illinois, Ste. 1100, Midland, TX 79701	8. Well No. 1
4. Well Location Unit Letter I : 660 Feet From The East Line and 1980 Feet From The South Line Section 16 Township 14-S Range 33-E NMPM Lea County	9. Pool name or Wildcat Saunders Permo Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4211.5' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Record: 13-3/8" at 415' (circulated cement)  
8-5/8" at 4120' (circulated cement)  
5-1/2" at 10140' (top of cement at 8900')  
Perforations from 9950-9998'

Proposed plugging procedure: 1) Pull 6000-6500' 5-1/2" casing  
2) CIBP & 35' cement on top @ 9900'  
3) 100' Stub plug at 6000' (tag)  
4) 100' cement from 4170-4070' (tag)  
5) 100' cement from 465-365'  
6) 10 sx at surface and install dry hole marker  
Mud between plugs 25#/bbl salt gel

Plugging to begin January 27, 1992.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sabra Fury TITLE Agent DATE 1/22/92  
TYPE OR PRINT NAME Sabra Fury TELEPHONE NO. 915/682-5216

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JAN 24 '92