

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**OIL CONSERVATION DIVISION**  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 322	
7. Unit Agreement Name	
8. Farm or Lease Name	
Lea "VF" State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Saunders Permo Upper Penn	
12. County	
Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator	
Gulf Oil Corporation	
3. Address of Operator	
P. O. Box 670, Hobbs, NM 88240	
4. Location of Well	
UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4209' GL	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Re-enter <sup>TA</sup> well &amp; sidetrack</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re-enter well and drill as close as possible to old hole by sidetracking to go around junk in hole which could not be removed because of collapsed casing. Original 5½" casing cut at approx 6250'; plug back to approx 6200'; sidetrack hole start at approx 6200'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R.D. Pite</u>	TITLE <u>Area Engineer</u>	DATE <u>4-14-82</u>
ORIGINAL SIGNED BY		
APPROVED BY <u>JERRY SEXTON</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

**APR 15 1982**