NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old .
ANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
ILE	The mexico of conservation commission	Effective 1-1-65
.s.g.s.	1	
AND OFFICE	1 .	5a. Indicate Type of Lease
	4	State X Fee
PERATOR .	. ·	5. State Oil & Gas Lease No.
SUNDR	RY NOTICES AND REPORTS ON WELLS	
USE "APPLICAT	TON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	·w· (
OIL CAS		7. Unit Agreement Name
werr   werr	OTHER- dry	·
Name of Operator		8. Farm or Lease Name
Maralo, Inc.		Samantha "7" State
Address of Operator -		9. Well No.
P. O. Box 83	32, Midland, Texas 79702 0832	
Location of Well		10. Field and Pool, or Wildcat
MAIT LETTER K	1080	1
Α.	1980 FEET FROM THE South LINE AND 1914	- rect from Baym-Upper Pennsylvaniar
	_	
West LINE, SECTION	ON	NMPM. (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
	4260 GR	Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Check 2	Appropriate Box To Indicate Nature of Notice, Repo	ort or Other Data
NOTICE OF IN		SEQUENT REPORT OF:
RFORM REMEDIAL WORK	PLUG AND ABANDON THE REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
LL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	
	OTHER	
OTHER		
Describe Proposed of Completed Opwork) SEE RULE 1103.	erations (Clearly state all pertinent details, and give pertinent dates	, including estimated date of starting any proposed
•		
1. Place a 144' plu	g (5sx - 6.5 cubic foot) from + 9880' to an	proximately 0736! in the 2.7/9"
1. Place a 144' plug (5sx - 6.5 cubic foot) from + 9880' to approximately 9736' in the 2 7/8"  ID liner. Pull tubing up and reverse out w/9.5#/gal mud laden fluid to displace casing		
iluid(s).		
2. Determine free po	oint of 5½" casing. March 1982 TOC 5100'.	Cut-off and recover essing
3. Place a 35 sx (45.5 cu ft. slurry, approximately 135' in 7 7/8" gauge hole) cement		
plug into stub of	f りち casing.	
4. Place a 55 sx cer	ment plug from 4126' to above 4026', 50' in	and out 8 5/8" surface casing
If unable to pull	1 5½" below 4126, it will be necessary to pe	erforate and squeeze this same
incerval.	<u>.</u>	
5. Place a 15 sx (5	7.7' in 8 5/8" casing) from + 57' to surface	e. Erect marker. Cleanup
location.	<b>-</b>	
	;	
		•
		•
	,	
hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
mat the information a	true and complete to the best of my knowledge and belief.	
$\mathcal{C}_{2}$		
" Overvour Co	Agent - TITLE Agent	
ORIGINAL SIGNED BY JES	RY SEXTON	
DISTRICT I SUPERV		MAY 2 9 1985
O/ED BY		ANDOLD FOR TO TAKE SON

DITIONS OF APPROVAL, IF ANY: