

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.  
LC-6467

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL  GAS WELL  OTHER

7. Unit Agreement Name

8. Farm or Lease Name  
Richardson Unit

9. Well No.  
1

10. Field and Pool, or Wildcat  
Wildcat

11. Location of Well  
UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM  
THE West LINE, SECTION 32 TOWNSHIP 13S RANGE 36E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)  
3976.0 GR

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/1/82 MI & RU CU. GIH w/2 3/8" to drill out DV tool @ 12346.  
7/2/82 Drill DV tool & tested csg. to 1500#/30 min.  
7/3/82 Drill & clean out to 13236'. POH. Lost cone in hole.  
7/4/82 Fish for Cone w/magnet on wireline. Lost magnet in hole, GIH w/os & 2 3/8" tbg. POH w/fish.  
7/7/82 GIH w/globe basket & 2 3/8" tbg & fish for cone. POH & rec cone.  
7/8/82 GIH w/newbit & drilled to 13370' - pkr shoe. Circ hole clean w/3% kcl. Clean out open hole from 13370 to 13407. POH.  
7/9/82 RU to log G/R, CBL, CCL from TD to 9030 TOC - GIH w/ 2 jts 2 3/8" tail pipe, Baker Loc Set pkr, On/Off tool, & 2 3/8" tbg.  
7/10/82 Set pkr @ 13,331 & RU tree - Swab test well.  
7/11/82 Swab test  
7/13/82 Acidize open hole w/1000 gal 20% - Swab back & flow tested well @ 1/4" choke @ 1800# FTP Shut well in.  
7/14/82 Release all rental equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul J. Sandoz TITLE Engineer DATE July 20, 1982

APPROVED BY JERRY SEXTON TITLE DISTRICT 1 SUPR DATE JUL 23 1982

CONDITIONS OF APPROVAL IF ANY:

RECEIVED

JUL 22 1982

G.C.D.  
HOBBS OFFICE