

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-5217	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
Sun Exploration & Production Co.		New Mexico "R" State
Address of Operator		9. Well No.
P.O. Box 1861 Midland, Texas 79702		3
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>K</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM		Cerca (Upper Penn)
THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>13-S</u> RANGE <u>34-E</u> NMPM.		
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
4142.4' GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH W/CIBP ON WL & SET AT 5250'. DUMP 4 SX CMT ON TOP OF CIBP.

CUT OFF 5-1/2" CSG AT 3100'. POH W/5-1/2" CSG, RIH W/2-7/8 WS AND SPOT 100' CMT PLUG 3150-3050'. PU TBG, WOC, TAG TOP OF PLUG.

SPOT 100' CMT PLUG 2000-1900 INSIDE 8-5/8" CSG. (TOP OF SALT SEC) PU & SPOT 100' CMT PLUG 528-428 INSIDE 8-5/8" CSG, POH

SPOT 10 SX CMT AT SURFACE, CUT OFF CSG 4' BELOW SURFACE. WELD ON STEEL PLATE, SET PERM MARKER, CLEAN UP LOCATION

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Accounting Asst. II DATE 2-8-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 10 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 9 1983

O.C.D.
HOBBS OFFICE