

COPIES RECEIVED	
LOCATION	
OFFICE	
DATE	

Form C-103
Supersedes Old
C-103 and C-103
Effective 10-68

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
C-7177	
7. Unit Agreement Name	
Robinson Unit	
8. Farm or Lease Name	
Robinson Unit Tr. 5-10	
9. Well No.	
10	
10. Field and Pool, or Wildcat	
Mail. Grayb. S. 4.	
12. County	
Lea	

ated Oil & Gas Co.

P.O. Box 637, Hobbs, New Mexico 88240

South

110

Lea

16

2

Check appropriate

NOTICE OF ABANDONMENT

4100 S.W.

and other Data

SUBSEQUENT REPORT OF

THROWING MUDS AREA ☐
REPAIRS OR ABANDON ☐
HOLE OR ALTER CASING ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

1. Set 5" 54' 3750'.

Spot 4 ex. cement on top 3" 1'.

2. Spot 35 ex. plug 470'.

3. Spot 50 ex. plug 450', 7" cut off and bottom of surface.

4. Spot 10 ex. plug - surface.

5. Install dry-hole marker. Above location.

Hole loaded with mud and plug dissolved w/mud.

I hereby certify that the information is true.

Agent

5/2/75

APPROVED BY

NOTATIONS OF APPROVAL, IF ANY