

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HUBBS OFFICE D. C. C.

MAY 31 8 11 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-3610	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Ryder Tool Management Corp.		8. Farm or Lease Name Phillips Texas State
3. Address of Operator 922 - 8th Street, Wichita Falls, Texas 76301		9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>1st</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17</u> RANGE <u>32</u> N.M.P.M.		10. Field and Pool, or Wildcat Maljamar
15. Elevation (Show whether DF, RT, GR, etc.) 424 G L		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JCB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

5-13-68 Pulled 1792' casing.
Set cast iron bridge plug @ 2240', capped w/1 sack cmt. (7')
Set 25 sx cmt. of casing stub, 1794'.
Set 25 sx cmt. @ base of surface pipe.
Set 10 sx cmt. to top of surface.
Set metal marker at well site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John Halsey</u>	TITLE <u>Agent</u>	DATE <u>May 29, 1968</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		