

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-029410 (2)
2. NAME OF OPERATOR Continental Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 468, Hobbs, N. Mex. 88240		7. UNIT AGREEMENT NAME MCA
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FEL of Sec. 29		8. FARM OR LEASE NAME MCA Unit No. 2
14. PERMIT NO.		9. WELL NO. 112
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3969' DF		10. FIELD AND POOL, OR WILDCAT MCA G-SB Refract
		11. SEC., T., R., OR BLK. AND SURVEY OR AREA Sec. 29 T-17S R-32E
		12. COUNTY OR PARISH Lea
		13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) **Clean out & Stimulate** ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pulled producing equipment. Cleaned out to TD. Set OH Plr @ 3871', and OH Plr. @ 3807'. Treated 3807' - 3871' w/250 gal. 15% HCl acid and 1,000 gal. 28% HCl acid. Swabbed well. Pulled OH Plr. plug back OH from 3871' to 3718' w/ 1/2" gravel. Set OH Plr. @ 3550'. Treated OH 3560' - 3775' w/500 gal. 15% HCl-HCl acid then fraced w/15,000 gal. Treated fresh water on 30,000# sand. Pulled OH Plr. Ran 6 1/4" bit and cleaned out to 4,070'. Re-ran producing equipment and placed well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert DeLuca

TITLE

Division Office Manager

DATE

1-18-74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

JAN 21 1974

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS-S, MCA-3, File