

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-10137</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State 245</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Lazy J-Penn</b>
12. County <b>Lea</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <b>OIL WELL</b> <input checked="" type="checkbox"/> <b>GAS WELL</b> <input type="checkbox"/> <b>OTHER</b> <input type="checkbox"/>
2. Name of Operator <b>Atlantic Richfield Company</b>
3. Address of Operator <b>Box 1978 Roswell, New Mexico 88201</b>
4. Location of Well UNIT LETTER <b>B</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>1650</b> FEET FROM THE <b>East</b> LINE, SECTION <b>28</b> TOWNSHIP <b>13 S</b> RANGE <b>33 E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4246' GR</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production from this well has declined to less than 20 BOPD + 98% water and the well is no longer economical to produce. We propose to P & A as follows:

Set 5½" CIBP @ 9560' & cap with 2 sx of cement.  
Cut off & recover 5½" casing from free point.  
Use 9#/gal. gel mud & spot these cement plugs:  
30 sx in & out of 5½" stub  
30 sx across 8-5/8" shoe at 4030'  
30 sx across 13-3/8" shoe at 322'  
10 sx in top of well

Dry hole marker will be erected. Location cleared & levelled & made ready for inspection.

*25 11 11*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <b>Dist. Dril. Supvr.</b>	DATE <b>3-23-71</b>
APPROVED BY <i>[Signature]</i>	TITLE <b>SUPERVISOR DISTRICT</b>	DATE <b>MAR 25 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

**MAR 22 1971**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**