

COPIES RECEIVED	
CONTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.  
E-605

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cities Service Oil Company	8. Farm or Lease Name State AP
3. Address of Operator Box 1919 - Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER J, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 15S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Caudill Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3914 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
PULL OR ALTER CASING   
OTHER

PLUG AND ABANDON   
CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK   
COMMENCE DRILLING OPNS.   
CASING TEST AND CEMENT JOB   
OTHER

ALTERING CASING   
PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned in the following manner:

- MIRU pulling unit and pulled rods and tubing.
- Set a CIBP @ 10,260' and dumped 5 sacks cement on top of CIBP @ 10,260' - 10,220'.
- Moved off pulling unit and MIRU casing pullers and loaded hole with mud laden fluid.
- Shot off and pulled 5430' of 5-1/2" casing.
- Displaced a 30 sack cement plug 1/2 in and 1/2 out of 5-1/2" stub from 5478' - 5378'.
- Displaced a 30 sack cement plug 1/2 in and 1/2 out of 8-5/8" casing shoe from 4700' - 4600'.
- Set a 10 sack cement surface plug in top of the 8-5/8" casing from 30' - 0' with a 4" dry hole marker extending 4' above the surface to designate a plugged and abandoned location.
- The location has been cleared of all material and debris.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. Spiller TITLE Region Oper. Mgr. DATE June 14, 1974

APPROVED BY John W. Remyon TITLE Geologist DATE June 14, 1974

CONDITIONS OF APPROVAL, IF ANY: