

(5) Prior to initiating injection operations within one-half mile of any of the wells shown on Exhibit "D", the applicant shall re-plug said wells in a manner which will assure that these wellbores will not serve as a conduit for migration of injected fluid to the satisfaction of the supervisor of the Hobbs district office of the Division.

EXHIBIT "D"
 CASE NO. 10154
 ORDER NO. R-9431

INADEQUATELY PLUGGED AND ABANDONED WELLS

<i>Operator</i>	<i>Lease</i>	<i>Well No.</i>	<i>Location</i>	<i>Sec-Twp-Rge</i>
Tidewater Associated Oil Co.	H.T. Monteith	1	1650' FSL - 2335' FWL	25-16-36
Cities Service	State AE	2	3630' FNL - 4290' FEL	36-16-36
Getty Oil Co.	State "M"	3	1650' FSL - 1650' FEL	36-16-36
Getty Oil Co.	State "P"	5	330' FSL - 330' FWL	32-16-37
Magnolia Petroleum Co.	State "R"	3	660' FNL - 660' FEL	02-17-36