

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>Inexco Oil Company</b>		8. Farm or Lease Name <b>Pan Am State</b>
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Co., Box 2010, Hobbs, N.M. 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>28</b> TOWNSHIP <b>16S</b> RANGE <b>33E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>U.K.</b>		12. County <b>Lea</b>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Spotted a 25 sx cement plug at 8-5/8 casing shoe at 4465'.
2. Spotted a 25 sx cement plug at top of salt at 1530'.
3. Spotted a 25 sx cement plug at 8-5/8 casing stub at 1100'.
4. Spotted a 25 sx cement plug at 13-3/8 casing shoe at 310'.
5. Spotted a 10 sx cement plug at surface with marker.
6. Hole was loaded with mud-laden fluids.
7. Well was plugged and abandoned on 7/20/71.

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Heimicker</i></u>	TITLE <b>Agent</b>	DATE <b>7/21/71</b>
APPROVED BY <u><i>Nathan E. Clegg</i></u>	TITLE <b>OIL &amp; GAS INSPECTOR</b>	DATE <b>FEB 11 1972</b>
CONDITIONS OF APPROVAL, IF ANY:		