

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

August 16, 1979

POST OFFICE BOX 1980 HOBBS, NEW MOXICO 68240 (505) 393-6161

American Petrofina Company of Texas Box 1311 Big Spring, Texas 79720

Gentlemen:

The bradenhead test on the John B-5 in Unit P of Section 26, T17S, R32E, Lea County, NM, shows communication between the 8 5/8 casing and 13 3/8" casing which indicates a hole in the 8 5/8" casing. For this reason, the 8 5/8" and $5\frac{1}{2}$ " annulus will have to be loaded with mud to stop the problem. After the mud is added a retest will be required to see that the problem is corrected.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton

Supervisor, District I

JS/ed