

August 31, 1979
3.00 PM

To whom it may Concern:

DUE to a blockage in the
hole drilled for HERNON OIL CO,
O.A. WOOLLEY LEASE, WELL #1, LEA CO, N.M.
I was unable to complete work survey
Requested by above client. Attempts to
pass through bridge in hole, I had
to shut down the tool joint to Tension
encountered. The well has been properly
operating.

A drift approximately a deviation
from 1° to 2° was noticed on
instrument logs. The direction
indicated was 320° magnetic North. The
maximum deviation detected was 3 1/2° at
approximately 10,000'. At 10,000' down
to 2° was observed at 11,400', the
depth the tool stopped. The AZ. north
of the drift remained at 320°.

Thank you

Robert Winters
501 1st St. N.
Wichita
KS 67208, TEXAS