

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
LG 1432

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Carr Well Service Inc.

3. Address of Operator  
PO Box 69090, Odessa Texas, 79769

4. Location of Well  
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE East LINE, SECTION 28 TOWNSHIP 16S RANGE 35E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name  
Eidson Com

9. Well No.  
1

10. Field and Pool, or Wildcat  
Shoobar Atoka

15. Elevation (Show whether DF, RT, GR, etc.)

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPWS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed plugging: Perfs 12,035 - 12,052

1. Set CIBP 11,935', cap with 35' cement
2. Load hole with 10# salt water gel
3. Shoot and pull 4½" casing at freepoint
4. Set 100' plug at casing cutoff (50' in 50' out of stub)
5. Set 100' plug at top of Glorieta
6. Set 100' plug at 9 5/8" casing shoe (50' in 50' out)
7. Set 100' plug at top of salt
8. Set 100' plug at conductor shoe
9. Set 10 sk. surface plug
10. Install dry hole marker and clean location

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE APPROVAL OF PLUGGING OPERATIONS FOR THIS WELL TO BE APPROVED.

915/686-8964

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Agent DATE 30 November 1988

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

DEC 14 1988

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 13 1988

U.S. DEPARTMENT OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION  
COMMUNICATIONS SECTION  
OCD  
HOBBS OFFICE