

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State For

5. State Oil & Gas Lease No.
LG 880

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

6. OIL WELL GAS WELL OTHER- Plug & Abandon

7. Unit Agreement Name

8. Farm or Lease Name
Etcheverry WD State

9. Well No.
1

10. Field and Pool, or Wildcat
Saunders Permo Upper Perm

1. Name of Operator
Yates Petroleum Corporation

2. Address of Operator
207 South 4th St., Artesia, NM 88210

3. Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 2310 FEET FROM
THE East LINE, SECTION 23 TOWNSHIP 15S RANGE 33E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4166' GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105.

Propose to plug and abandon well as follows:

- Plug #1: Set 40 sx cement at 10150-10050'
- Plug #2: Set 40 sx cement at 8000-7900'
- Plug #3: Set 40 sx cement at 5300-5200'
- Plug #4: Set 35 sx cement at 4270-4170'
- Plug #5: Set 25 sx cement at 1650-1550'
- Plug #6: Set 10 sx cement at 50'-Surface

Install dry hole marker.
Verbal permission for plugging procedure given by Mr. Jerry Sexton, OCD, Hobbs, NM, 6-17-83.

Heavy mud will be placed between plugs. Surface restored according to regulations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor DATE 6-17-83

**ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR**

JUN 20 1983

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: