

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

- DISTRICT I**
P. O. Box 1980 Hobbs, NM 88240
- DISTRICT II**
P. O. Drawer DD, Artesia, NM 88210
- DISTRICT III**
1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-025-28792
5. Indicate Type or Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	GOODRICH UNIT
8. Well No.	#1
9. Pool name or Wildcat	AUSTIN MISSISSIPPIAN, SOUTHWEST

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well
OIL WELL GAS WELL OTHER

2. Name of Operator
Harvey E. Yates Company

3. Address of Operator
P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Well Location
Unit Letter J : 1,980 Feet From The SOUTH Line and 1,980 Feet From The EAST Line

Section	11	Township	15S	Range	35E	NMPM	LEA	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3972.3' GR (15.3' KB)								

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

TOC @ 10,800' BY CBL
CURRENT PERFS: 12,893-933'

POOH w/ TBG & PKR. GIH & SET CIBP @ 12850' PLUS 35' CMT.
FREE POINT CSG & ATTEMPT TO RECOVER 10,500'+/- OF CSG.
LAY DOWN CSG & GIH w/ TBG. SPOT 100' PLUG ACROSS STUB. (50' IN & OUT).
TAG STUB PLUG.
SPOT 100' PLUG @ 9721' (TOP OF WOLFCAMP)
SPOT 100' PLUG @ 6150' (TOP OF GLORIETA)
SPOT 200' PLUG @ 4700' (ACROSS INTERM. SHOE @ 4619')
SPOT 100' PLUG @ 2300'
SPOT 100' PLUG @ 420' (ACROSS SURFACE SHOE @ 370')
SPOT 60' PLUG @ SURFACE.
INSTALL DRYHOLE MARKER.

AFOREMENTIONED APPROVED BY PAUL KAUTZ w/ OCD-I 7-19-96rfn
CALL OCD-I (HOBBS) @ 1-505-393-6161 24 HOURS PRIOR TO COMMENCEMENT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER. Date 3/12/97
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use)
APPROVED BY JERRY SEXTON Title _____ Date MAR 17 1997
Conditions of approval, if any: _____

SE

CP