

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2000
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1733

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SAG TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Unit VACUUM GRAYBURG SAN ANDRES
2. Name of Operator TEXACO PRODUCING INC.	6. Form or Lease Name
3. Address of Operator P.O. Box 728, HOBBS, NEW MEXICO 88240	9. Well No. 43
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>NORTH</u> LINE AND <u>484</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>1</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat VACUUM GRAYBURG SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) GR	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUS AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUS AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>BRDNHD. SQZ.</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① RIGUP PULLING UNIT, POH W/ SUB AND TBG.
- ② TIH W/ CIBP, SET @ 100' ABOVE 5 1/2" C&G. SHOE, LOAD HOLE AND TEST CIBP, SPOT 2 SKS, SAND, POH.
- ③ PERF ~ 1505' - 1510' W/ (KONE) JET SACT (NOT IN COLLAR).
- ④ TIH W/ P&R AND TBG, SET @ 1400', ATTEMPT TO CIRC. TO SURFACE THROUGH FLOW CHANNEL, AND/OR ESTB. PUMP-IN RATE, POH W/ P&R AND TBG.
- ⑤ TIH W/ CEMENT RETAINER SET @ 1400'.
- ⑥ PUMP 400 SKS, CLASS "C" W/ 2% C&C AND 1500 GALS. FLO-CHEK IN THREE STAGES, CIRC. CEMENT TO SURFACE, ST SURFACE VALVE AND SQUEEZE LAST 200 SKS DOWN CHANNEL.
- ⑦ DOC AND TEST, AND IF NECESSARY RESQUEEZE.
- ⑧ TIH W/ SUB PUMP AND RETURN TO PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____	TITLE <u>AREA SUPERINTENDENT</u>	DATE <u>4-26-88</u>
A. GERANDT (393-4031) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		