

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-0225-07520

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P, Inc.

3. Address of Operator

P. O. BOX 576 (WCK 5237), HOUSTON, TX 77001

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT

8. Well No.

221

9. Pool name or Wildcat

HOBBS (G/SA)

4. Well Location

Unit Letter F : 1650 Feet From The NORTH Line and 2310 Feet From The WEST Line

Section 32 Township 18S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3644' KB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: PB SAN ANDRES: OPEN GRAYBURG ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-22 TO 6-28-94:

POH W/PROD EQMT. CO TO 4130'. SET CIBP @ 4050'. PULLED "GUTS" OUT OF CIBP & HAD TO SET ANOTHER CIBP @ 4048'. PERF GRAYBURG 3864' - 3956' (1 SPF). SET RBP @ 3972', PKR @ 3942'. PMPD 120 GAL 28% AS-66 HCL INTO PERFS. SPOT 380 GAL ACID DOWN TO BTM OF PKR. REL PKR & RBP. RESET RBP @ 3942'. RESET PKR @ 3912'. SPOT 1000 GAL 28% AS-66 HCL DOWN TO PKR. PMPD 120 GAL ACID INTO FM. PKR OR PERFS BEGAN COMM. REVERSED REMAIN'G ACID OUT INTO TRUCK. REL PKR & RESET @ 3874'. PMPD INTO PERFS, COMM AGAIN. REL TOOLS, POH. RIH W/RBP & PKR. TAG CIBP @ 4044'. (HAD USED INCORRECT TALLY IN PREV OPERATIONS. WAS SETTING PKR & RBP 30' OFF.) SET RBP @ 3972' & PKR @ 3908'. ACD PERFS 3922-56' W/1500 GAL 28% AS-66 HCL. REL TOOLS. RESET RBP @ 3908' & PKR @ 3790'. ACD PERFS 3864' - 3905' W/2000 GAL 28% AS-66 HCL. REL TOOLS & POH. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. G. S. Nady

TITLE

MGR - ASSET ADMIN.

DATE 4/26/95

TYPE OR PRINT NAME

G. S. NADY

TELEPHONE NO. 713/544-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 01 1995