

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 24 3 41 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator <b>Gulf Oil Corporation</b>		8. Firm or Lease Name <b>W. D. Crimes /NCT-A/</b>	
3. Address of Operator <b>Box 670, Hobbs, New Mexico</b>		9. Well No. <b>12</b>	
4. Location of Well UNIT LETTER <b>L</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>18-S</b> RANGE <b>38-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Bowers</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3645 GL</b>		12. County <b>Lea</b>	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

**Plugged and abandoned.**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**3234' TD.**

Pulled rods, pump and tubing. Ran 7" BP on tubing and set at 3092'. Displaced hole with 9.2# mud. Tested CI BP and casing with 500#, 10 minutes. OK. Spotted 10 sack cement plug on top of BP from 3092' to 3038'. Spotted 10 sack cement plug from 60' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned March 24, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements TITLE Area Production Manager DATE March 24, 1966

APPROVED BY Leslie A. Clements TITLE Area Production Manager DATE 1966

CONDITIONS OF APPROVAL, IF ANY: