

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAINTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-8714

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR APPLICATIONS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Water Injection Well**

1. Name of Operator
Murphy H. Baxter

2. Address of Operator
P. O. Box 2040 Midland, Texas 79702

3. Location of Well
UNIT LETTER **G** **1650** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **7** TOWNSHIP **18S** RANGE **34E** N.M.P.M.

15. Elevation (Show whether DF, RT, CR, etc.)
4097' DF

7. Unit Agreement Name
N. EK Queen Unit

8. Farm or Lease Name
Tract 4

9. Well No.
7

10. Field and Pool, or Wildcat
E. K Yates 7 Rivers Queen

12. County
Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Commission will be notified 24 hrs. to commencing work.

1. Trip in hole with CIBP. Set CIBP @ 4325.
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1700'. (Top of anhydrite @ 1732'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag and test plug to 500#'s.
6. Spot 50' of cement above and below surface casing shoe @ 330'. WOC.
7. Tag plug. Cut off bradenhead and weld steel plate on casing. Set P & A marker.

10 sack surface plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Sledge TITLE Petroleum Engineer DATE 8-13-87

APPROVED BY Paul Kautz TITLE Geologist DATE AUG 24 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 24 1987
HQSBS OFFICE